

Queen's Garden Inspection – Date: 14-2-24

Item	Condition/risk	Notes
Carousel	ok	
Multi Component	ok	
Cradle Swings	ok	
Flat Seat Swings	ok	
Spring Lion Rocker	ok	
Spring Frog Rocker	ok	
Picnic Table	ok	
Playground bin	ok	
Playground Bench	ok	
Millennium Bench	ok	(By Church)
Queen's Bench	ok	(by Football goal)
Plank Bench	ok	
Basket Ball	Low	Back panel deteriorating but still secure
Football Goal	ok	
Samba Goal	ok	
Bin near gate	ok	
Fencing	Low	14-2-24 Gate to church has lost its 'stop'
Portakabin Stores	ok	(not EPC property)
Flag pole	ok	
Notice Board	ok	